

Audit Attestation for

Multicert - Serviços de Certificação Electrónica, S.A.

Reference: DTNQ.2019.001/06

Porto - Portugal, 2021-07-17

To whom it may concern,

This is to confirm that APCER - Associação Portuguesa de Certificação has audited the CAs of the Multicert - Serviços de Certificação Electrónica, S.A., without critical findings.

This present Audit Attestation Letter is registered under the reference DTNQ.2019.001/06 and consists of 9 pages.

Kindly find here below the details accordingly.

In case of any question, please contact: APCER - Associação Portuguesa de Certificação O 'Porto Bessa Leite Complex | Rua António Bessa Leite, 1430 - 1º Esq., 4150-074 Porto E-Mail: info@apcer.pt Phone: +351 229 993 600 www.apcergroup.com

With best regards,

Paulo Borges Lead Auditor *José Leitão* APCER CEO

This attestation is based on the template version 2.8 as of 2021-04-21, that was approved for use by ACAB-c.



Identification of the conformity assessment body (CAB):	 APCER - Associação Portuguesa de Certificação O 'Porto Bessa Leite Complex Rua António Bessa Leite, 1430 - 1º Esq., 4150-074 Porto Accredited by IPAC under registration C0009 for the certification of trust services according to ETSI EN 319 403-1 V2.3.1 (2020-06), ETSI TS 119 403-2 v1.2.4 (2020-11), ETSI TS 119 403-3 v1.1.1 (2019-03) respectively. (<u>http://www.ipac.pt/pesquisa/ficha_ocp.asp?id=C0009</u>) Insurance Carrier: Hiscox, S.A. Insurance policy number: 2018868
Identification and qualification of the audit team:	 Number of audit team members: 1 Audit members identification: Paulo Jorge Martins Borges Academic qualifications of team members: Degree in Electrotechnical Engineering PECB Senior ISO 27001 Lead Auditor PECB Senior ISO 22301 Lead Auditor PECB Senior Cybersecurity Manager PECB ISO 20000 Lead Auditor PECB ISO 20000 Lead Auditor PECB ISO 20000 Lead Auditor PECB Senior Cybersecurity Manager PECB ISO 20000 Lead Auditor PECB Management Systems Auditor PKI Auditor since 2006, with more than 40 international audits elDAS Auditor since 2016, with more than 20 international audits Uptime Institute Datacenter ATS and AOS Expert Additional competences of team members: 36 years of international ICT and Information Security consultancy, training, and audits PECB Iso 27001 certification auditor since 2012 APCER ISO 27001 certification auditor since 2012 APCER ISO 27001, ISO 22301, ISO 20000, Cybersecurity and SCADA APCER ISO 27001, Certification auditor since 2018 ISO 31000 and ISO 27005 Risk Management Expert National Security Auditor accredited by GNS (Portuguese eIDAS Supervisor Body) Portuguese navy officer responsible for fleet communications encryption 12 years as IBM Mainframes systems engineer Extensive knowledge of ETSI standards English and French reading and writing rate A Types of professional experience and practical audit experience: The CAB ensures, that its personnel performing audits maintains competence on the basis of appropriate education, training or experience; that all relevant experience is current and prior to assuming responsibility for performing as an auditor, the candidate has gained experience in the entire process of CA/TSP auditing.
	 Auditors code of conduct incl. independence statement: Code of Conduct as of Annex A, ETSI EN 319 403-1.



management:

Identification of the	Identification of the	Multicert - Serviços de Certificação Electrónica, S.A.	1
	trust service provider	Lagoas Park - Edifício 3, Piso 3	
(TSP):	(TSP):	2740-266 Porto Salvo – Oeiras	
		Portugal	

Audit Period covered for all policies:	2020-04-07 to 2021-04-06
Audit dates:	2021-04-12 to 2021-04-21 (full audit period, on remote) 2021-04-14 and 2021-04-15 (on site)
Audit Location:	Registration Authorities – PORTO and LISBON (on site and remote) CA and personalization services – PORTO and LISBON (on site) Dissemination Services – PORTO and LISBON (remote) Revocation Services – PORTO (remote)



Identification of the audited Root-CA:	Name of the root, e.g. common Name	
MULTICERT Root Certification Authority 01	Distinguished Name	CN = MULTICERT Root Certification Authority 01 O = MULTICERT - Serviços de Certificação Electrónica S.A. C = PT
	SHA-256 fingerprint	604D32D036895AED3BFEFAEB727C009EC0F2B3CDFA42A1C71730E6A72C3BE9D4
	Certificate Serial number	544DA5BC4035565A
	Applied policy	Multicert Certification Practices Statement (v10.0) Multicert Certificate Policy (v6.0)

The audit was performed as full period of time audit at the TSP's location in Lisbon and Porto, Portugal.

It took place from 2021-04-12 to 2021-04-21 and covered the period from 2020-04-07 to 2021-04-06.

The audit was performed according to the European Standards:

"ETSI EN 319 411-1, V1.2.2 (2018-04)" and "ETSI EN 319 401, V2.2.1 (2018-04)"

as well as CA Browser Forum Requirements:

"Baseline Requirements, version 1.7.4"

and considering the requirements of the:

"ETSI EN 319 403-1 V2.3.1 (2020-06)" and "ETSI TS 119 403-2 V1.2.4 (2020-11)" for the Trust Service Provider Conformity Assessment.

This attestation is based on the template version 2.8 as of 2021-04-21, that was approved for use by ACAB-c.

The full annual audit was based on the following policy and practice statement documents of the TSP:

- 1. Multicert Certification Practices Statement, version 10.0, as of 2020-12-17
- 2. Multicert Certificate Policy (v6.0), version 6.0, as of 2020-12-17

In the following areas, non-conformities have been identified throughout the audit:

Findings about ETSI EN 319 401:

5. – Risk Assessment

Requirement REQ-5-04

The existence of risk treatment measures with outdated dates was evidenced, without proper justification, without identification of a new implementation date, nor identification of the possible impacts of non-compliance with the execution dates.

6.1 – Trust Service Practice Statement

Requirements REQ-6.1-03, 04 and 08

The "back office" tool was used by the External Registration Authority was replaced in December 2020.

This change was executed in an uncontrolled manner in relation to the functional and safety practices identified in the current Multicert procedure.

7.6 - Physical and environmental security

Requirements REQ.7-01; REQ.8-01, 02, 03, 05 and 08

The use of a communications equipment (4G router) at HAS (High Security Area) level 3 was detected to support the execution of the installation of new servers.

It was evidenced that this implementation was carried out without the respective risk analysis, adequate security controls for the described objective, nor obtained the respective authorization for the use of wireless communications.

In addition, the audited risk analysis does not identify any risk situation regarding the use of level 3 for this type of staging, nor for the support of 4G wireless communications.

Findings about ETSI EN 319 411-1:

None.

Findings about ETSI EN 319 411-2:

None.

All non-conformities have been closed before the issuance of this attestation.

This Audit Attestation also covers the following incidents as documented under for non-qualified digital services:

• Bug 1680083, Camerfirma: certificate with an incorrect OrganizationName

https://bugzilla.mozilla.org/show_bug.cgi?id=1680083

• Bug 1637093, Multicert: AIA CA Issuer field pointing to PEM encoded cert

https://bugzilla.mozilla.org/show_bug.cgi?id=1637093

The remediation measures taken by MULTICERT as described on Bugzilla (see link above) have been checked by the auditors and properly addressed the incident.

The long-term effectiveness of the measures will be rechecked at the next regular audit.

The Sub-CA that has been issued by the aforementioned Root-CA and that have been covered by this audit are listed in table 1 below.

The TSP assured that all non-revoked Sub-CA that are technically capable of issuing server or email certificates and that have been issued by this Root-CA are in the scope of regular audits.



Intermediate CA	Trust Service	Distinguished Name	SHA-256 fingerprint	Applied policy OID	EKU
MULTICERT Certification Authority 002	Non-Qualified Electronic Signatures	CN = MULTICERT Certification Authority 002 OU = Accredited Certification Authority O = MULTICERT - Serviços de Certificação Electrónica S.A. C = PT	914A87BDB2B35F73AEF7C213309A23 0921CD182C5668A6B5C4BE9BFF6A1 C03B3	EN 319 401 v2.2.1 EN 319 411-1 v1.2.2 (LCP, NCP, NCP+) ETSI TS 119 412-1 v1.3.1	not defined
MULTICERT Advanced Certification Authority 001	Non-Qualified Electronic Signatures	CN = MULTICERT Advanced Certification Authority 001 OU = Certification Authority O = MULTICERT - Serviços de Certificação Electrónica S.A. C = PT	EF72A054691F855D52A31988439B75 BDE49F03899ADF0EBC142CB96E3483 D6F7	EN 319 401 v2.2.1 EN 319 411-1 v1.2.2 (LCP, NCP, NCP+) ETSI TS 119 412-1 v1.3.1	not defined
MULTICERT Advanced Certification Authority 005	Non-Qualified Electronic Signatures	CN = MULTICERT Advanced Certification Authority 005 OU = Certification Authority O = MULTICERT - Serviços de Certificação Electrónica S.A. C = PT	24EDD4E503A8D3FDB5FFB4AF66C88 7359901CBE687A5A0760D10A08EED9 9A7C3	EN 319 401 v2.2.1 EN 319 411-1 v1.2.2 (LCP, NCP, NCP+) ETSI TS 119 412-1 v1.3.1	1.3.6.1.5.5.7.3.2 (id-kp-clientAuth) 1.3.6.1.5.5.7.3.4 (id-kp- emailProtection)
MULTICERT SSL Certification Authority 005 Note: Signed by MULTICERT Root Certification Authority 01	Non-Qualified Website Authentication	CN = MULTICERT SSL Certification Authority 005 OU = Certification Authority O = MULTICERT - Serviços de Certificação Electrónica S.A. C = PT	41E1F1B8DBDD05D8AD04F2CA8A734 2F461D99D79E7B466D49284B1909C2 8E2D8	EN 319 401 v2.2.1 EN 319 411-1 v1.2.2 (LCP, OVCP) Cab/Forum Baseline Requirements for the Issuance and Management of Publicly Trusted Certificates v1.7.4	1.3.6.1.5.5.7.3.1 (id-kp-serverAuth) 1.3.6.1.5.5.7.3.2 (id-kp-clientAuth)

WWW.APCERGROUP.COM | Phone number: 229 993 600



Intermediate CA	Trust Service	Distinguished Name	SHA-256 fingerprint	Applied policy OID	EKU
MULTICERT SSL Certification Authority 005 Note: Signed by Global Chambersign Root – 2008	Non-Qualified Website Authentication	CN = MULTICERT SSL Certification Authority 005 OU = Certification Authority O = MULTICERT - Serviços de Certificação Electrónica S.A. C = PT	0F17E376FE94E582D6EE649CDC516F F977E765C561AE087F31A3F5E8E66C CECD	EN 319 401 v2.2.1 EN 319 411-1 v1.2.2 (LCP, OVCP) Cab/Forum Baseline Requirements for the Issuance and Management of Publicly Trusted Certificates v1.7.4	1.3.6.1.5.5.7.3.1 (id-kp-serverAuth) 1.3.6.1.5.5.7.3.2 (id-kp-clientAuth)
MULTICERT SSL Certification Authority 001 Note: Signed by MULTICERT Root Certification Authority 01	Non-Qualified Website Authentication	CN = MULTICERT SSL Certification Authority 001 OU = Certification Authority O = MULTICERT - Serviços de Certificação Electrónica S.A. C = PT	FF453A5413EA558FE7062AB6FE8310 73E7F30FE6BA75B82EAD5209DB0775 CAD0	EN 319 401 v2.2.1 EN 319 411-1 v1.2.2 (LCP, OVCP) Cab/Forum Baseline Requirements for the Issuance and Management of Publicly Trusted Certificates v1.7.4	not defined
MULTICERT SSL Certification Authority 001 Note: Signed by Global Chambersign Root - 2008	Non-Qualified Website Authentication	CN = MULTICERT SSL Certification Authority 001 OU = Certification Authority O = MULTICERT - Serviços de Certificação Electrónica S.A. C = PT	06A57D1CD5879FBA2135610DD8D72 5CC268D2A6DE8A463D424C4B9DA89 848696	EN 319 401 v2.2.1 EN 319 411-1 v1.2.2 (LCP, OVCP) Cab/Forum Baseline Requirements for the Issuance and Management of Publicly Trusted Certificates v1.7.4	1.3.6.1.5.5.7.3.1 (id-kp-serverAuth) 1.3.6.1.5.5.7.3.2 (id-kp-clientAuth)

Table 1: Sub-CA's issued by the Root-CA or its Sub-CA's

This attestation is based on the template version 2.8 as of 2021-04-21, that was approved for use by ACAB-c.



Modification record

Version	Issuing Date	Changes
Version 1	2021-07-17	Initial Attestation

End of the audit attestation letter.